


Running Geomagic Design X in Go and Plus Mode


Running Geomagic Design X in Go Mode

1. Install Design X 2024.3.0 if it's not already installed.
2. Copy-paste the Design X 2024.3.0 shortcut on the desktop.
3. Rename the shortcut to Design X Go 2024.3.0.
4. Right-click on the Design X Go 2024.3.0 shortcut and click Properties.



a.


- Depending on the installation location of Design X, change the Target in the Shortcut tab in the Properties window to **"C:\Program Files\3D Systems\Geomagic Design X 2024.3.0\GeomagicDesignX.exe" /Go** or **C:\Program Files\Oqton\Geomagic Design X 2024.3.0\GeomagicDesignX.exe" /Go**



- Click OK.
- Double-click the icon to start Design X in Go mode.


Running Geomagic Design X in Plus Mode

1. Install Design X 2024.3.0 if it's not already installed.
2. Copy-paste the Design X 2024.3.0 shortcut on the desktop.
3. Rename the shortcut to Design X Plus 2024.3.0.
4. Right-click on the Design X Plus 2024.3.0 shortcut and click Properties.



5. Depending on the installation location of Design X, change the Target in the Shortcut tab in the Properties window to **"C:\Program Files\3D**

Systems\Geomagic Design X 2024.3.0\GeomagicDesignX.exe" /Plus or
**C:\Program Files\Oqton\Geomagic Design X
2024.3.0\GeomagicDesignX.exe" / Plus**



6. Click OK.

7. Double-click the icon to start Design X in Plus mode.